



STONE TECHNICAL SERVICES LTD
Kellaw Road
Darlington
Co. Durham
DL1 4YA



HEAD OFFICE: KELLAW ROAD | DARLINGTON | CO. DURHAM DL1 4YA
TEL: 01325 282794 | **FAX:** 01325 487329 | **MOB:** 07971 173626

SOUTHERN OFFICE: EVANS HOUSE | 107 MARSH ROAD | PINNER | MIDDX HA5 5PA | **TEL:** 0208 4296700 | **FAX:** 0208 4296755

NEWCASTLE OFFICE: TEL/FAX: 0191 496 1540

E-MAIL: ENQUIRIES@STONESERVICESUK.COM
WEB: WWW.STONETECHNICALGROUP.CO.UK
 WWW.STONESERVICESUK.COM

FREEPHONE: 0800 0480 151 FAX: 0800 0480152



Chimneys



Chimneys

Surveys Structural Photographic Digital CCTV

Ultrasonic/NDT testing of materials in situ.

Materials inspection, eg. steelwork, joints, welds, insulation and weather cladding.

CCTV and video filming or photographic surveying including two-way radio connections between the camera technician and ground level monitor screen, where required.

Full written reports with photographs, etc. and if requested details of recommendations for planned maintenance submitted.



Tall buildings, structures, steel, chimney, shafts and flare-stacks (above and below ground) require specialised access. This may be for inspection, alteration or maintenance purposes.

Due to the awkwardness or heights of the inspection works the client may not be able to be authorised by insurance to carry out such tasks.

Our experienced technicians/managers are keen to undertake these tasks liaising with the client to fulfill their requirements, eg. carbonation, core drilling, reinforcement location tests on concrete. Masonry inspection checking for loose or spalling materials or misalignment, erosion and corrosion, weather damage, structural faults, etc.



I am interested in the following,

- Steel chimney**
- Masonry chimney**
- Brick chimney**
- Concrete chimney**
- Other type**

Contact Details
Please fill in below and return.

Name:

Address:

.....

Tel:

Fax:

Email: